CVP-2002-00003 Rev. 0

0553966

Attachment ES-1

Waste Site Reclassification Form

Truste one neolassineation form		
Date Submitted: 07/24/02	Operable Unit(s): 100-BC-1	Control Number: 2002-046
Originator: R. A. Carlson	Waste Site ID: 116-B-7, 132-B-6, 132-C-2 B/C Outfalls	Lead Agency: EPA
Phone: 372-9632	Type of Reclassification Action:	
	Rejected Closed Out Interim Closed Out No Action	
This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed out, or no action and authorizing backfill of the site, if appropriate. Final removal from the National Priorities List (NPL) of no action or closed-out sites will occur at a future date.		
Description of current waste site condition:		
Remedial action at this site has been performed in accordance with remedial action objectives and goals established by the U.S. Environmental Protection Agency and the Washington State Department of Ecology, in concurrence with the U.S. Department of Energy, Richland Operations Office. The selected remedial action involves (1) excavating the site to the extent required to meet specified soil cleanup levels, (2) disposing of contaminated excavation materials at the Environmental Restoration Disposal Facility at the 200 Area of the Hanford Site, and (3) backfilling the site with clean soil to adjacent grade elevations. The excavation and disposal activities have been completed.		
Basis for reclassification:		
The 116-B-7, 132-B-6, and 132-C-2 B/C Outfall sites have been remediated to meet the cleanup standards specified in the <i>Interim Action Record of Decision for the 100-BC-1,100-BC-2, 100-DR-1, 100-DR-2, 100-FR-1, 100-FR-2, 100-HR-1, 100-HR-2, 100-HR-2, 100-IU-2, 100-IU-6, and 200-CW-3 Operable Units, Hanford Site, Benton County, Washington.</i> Remedial actions were performed to allow rural-residential use of shallow zone soils (i.e., surface to 4.6 m [15 ft] deep) and to protect groundwater and the Columbia River. The basis for reclassification is described in detail in the <i>Cleanup Verification Package for the 116-B-7, 132-B-6, and 132-C-2 B/C Outfalls</i> (CVP-2002-00003), Bechtel Hanford, Inc., Richland, Washington.		
(1) The 2		
DOE Project Manager	Shinakire Cara	Date
NA Ecology Project Manager	Signature (1)	Date :
L代NMS その EPA Project Manager	Signature	TEMPLE Date:
	的现在分词是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	

